Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1135	alpha near3 (ta or tantalum)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/05 15:01
L2	579	L1 and (alcu or copper or cu)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/05 15:01
L3	330	L2 and (rough\$4 or bump or uneven or porous or grain)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/05 15:01
L4	223	L3 and (tan or (tantalum adj1 nitride))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/05 15:01
L5	4	("6221757"   "6291885"   "6342448"   "6562715").PN. OR ("6727592").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/12/05 15:02
L6	3	L5 and (rough\$4 or bump or uneven or porous or grain)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/05 15:02
L7	271	vu near1 hung	US-PGPUB; USPAT	OR	OFF	2005/12/05 15:02
L8	121	L7 and (copper or cu)	US-PGPUB; USPAT	OR	OFF	2005/12/05 15:02
L9	69	L7 and (tantalum or ta)	US-PGPUB; USPAT	OR	OFF	2005/12/05 15:02
L10	54	L8 and L9	US-PGPUB; USPAT	OR	OFF	2005/12/05 15:02
L12	28	L10 and (rough\$4 or bump or uneven or porous or grain)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/05 15:04

L13	330	L2 and (rough\$4 or bump or uneven or porous or grain)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/05 15:05
L14	355	12 or 13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/05 15:04

L1	FILE 'REGISTRY' ENTERED AT 17:43:48 ON 01 DEC 2005 1 SEA ABB=ON PLU=ON TANTALUM/CN
L2 L3	FILE 'REGISTRY' ENTERED AT 17:44:09 ON 01 DEC 2005  1 SEA ABB=ON PLU=ON ALPHA(W)(TA OR TANTALUM)  0 SEA ABB=ON PLU=ON L1(L)ALPHA  D L2 ALL
L4	FILE 'HCAPLUS' ENTERED AT 17:45:02 ON 01 DEC 2005 284 SEA ABB=ON PLU=ON ALPHA(W)(TA OR TANTALUM)
L5 L6	FILE 'REGISTRY' ENTERED AT 17:45:28 ON 01 DEC 2005 608 SEA ABB=ON PLU=ON TANTALUM NITRIDE 2501 SEA ABB=ON PLU=ON TA/ELS, MAC AND NITRIDE
L7 L8 L9 L10 L11 L12	FILE 'HCAPLUS' ENTERED AT 17:46:31 ON 01 DEC 2005 7374 SEA ABB=ON PLU=ON (L5 OR L6) OR (TA OR TANTALUM) (W) NITRIDE 44 SEA ABB=ON PLU=ON L4 AND L7 2 SEA ABB=ON PLU=ON L8 AND ROUGH######### 18 SEA ABB=ON PLU=ON L8 AND BARRIER 2 SEA ABB=ON PLU=ON L8 AND OPENING 2 SEA ABB=ON PLU=ON L8 AND (FILL#### OR PLUG### OR OPENING) (3 A) (CU OR COPPER) 7 SEA ABB=ON PLU=ON L10 AND SURFACE 8 SEA ABB=ON PLU=ON L9 OR L11 OR L12 OR L13 D BIB AB HITSTR TOT
L15	FILE 'JICST-EPLUS' ENTERED AT 17:50:06 ON 01 DEC 2005 15 SEA ABB=ON PLU=ON ALPHA(W)(TA OR TANTALUM) D ALL TOT
	FILE 'INSPEC' ENTERED AT 17:50:58 ON 01 DEC 2005
L16	103 SEA ABB=ON PLU=ON ALPHA(W)(TA OR TANTALUM)
L17	430 SEA ABB=ON PLU=ON (TA OR TANTALUM) (W) NITRIDE
L18	8 SEA ABB=ON PLU=ON L16 AND L17 D ALL TOT
L19	846 SEA ABB=ON PLU=ON TAN/CHI
L20	12 SEA ABB=ON PLU=ON L16 AND L19
L21	11 SEA ABB=ON PLU=ON L20 NOT L18
L22	0 SEA ABB=ON PLU=ON L21 AND ROUGH####### 3 SEA ABB=ON PLU=ON L21 AND SURFACE
L23 L24	3 SEA ABB=ON PLU=ON L21 AND SURFACE 9 SEA ABB=ON PLU=ON L21 AND BARRIER
L25	9 SEA ABB=ON PLU=ON L21 AND BARRIER  9 SEA ABB=ON PLU=ON L22 OR L24
ب ے بد	. J OLD ON THE ON HEE ON HEE